

DANGER:

Contains Citrus Terpene (5989-27-5), Nonylphenol Ethoxylate (127087-87-0) and Carbon Dioxide Propellant (124-38-9). Do not use near heat, sparks or open flame. Avoid contact with eyes or prolonged contact with skin. Do not puncture or incinerate container. Do not expose to heat or store at temperatures above 120°F.

FIRST AID

IF SWALLOWED: Do not induce vomiting. Get medical attention.

IF EYE CONTACT: Flush with water for 15 minutes, lifting upper and lower lids. Get medical attention.

IF SKIN CONTACT: Wash affected area immediately with soap and water. If irritation persists, get medical attention.

HMIS RATINGS: Health; 1, Flammability; 2, Reactivity; 0, Personal Protection, B.

**KEEP OUT OF REACH
OF CHILDREN**

Manufactured for:

Direct Chem
A Division of Zircon Industries

**P.O. Box 22483
Cleveland, OH 44122**

**Phone: 216-581-7570
Fax: 216-581-2868**



SUPER ORANGE

TAR & ASPHALT REMOVER

WITH THE ALL-NATURAL CLEANING POWER OF D'LIMONENE

NET WT. 16 OZ. (1 LB.) (453 Grams)

DANGER:
EXTREMELY FLAMMABLE
HARMFUL OR FATAL IF SWALLOWED
CONTENTS UNDER PRESSURE
SEE OTHER CAUTIONS ON BACK PANEL

ENVIRONMENTALLY SAFE
BIODEGRADABLE
ALL NATURAL INGREDIENTS

NO TOXIC FUMES
NON-ACID • NON-CAUSTIC
NON-CORROSIVE

SUPER ORANGE uses the power of all-natural solvents to power through grease and oil, d'limonene, an orange peel extract, is so powerful, it will even remove tar and asphalt from tools and equipment, yet will not harm most paints. Use SUPER ORANGE as an oven and grill cleaner, laundry pre-spotter, decal remover, adhesive remover, printing ink remover and odor counteractant. SUPER ORANGE's non-staining formula will also remove gum and wax from rugs, carpets, upholstery and other fabrics.

USE ON:

Auto Motors, Garbage Cans and Trucks, Dumpster, Concrete, Masonry, Road, Farm and Construction Equipment

NOTE:

Do not spray into or on electrical equipment. Pretest on paints and plastics.

DIRECTIONS:

Direct actuator at area to be degreased, holding can approximately 8 inches away. Spray liberally. Allow to penetrate grease, tar or grime. For heavy deposits, allow extra time. For stubborn spots, agitate with a brush. Wipe area clean with a damp cloth or rinse thoroughly with water.